



ASIAN TESTING & INSPECTION SERVICES

Approved by Govt. Organizations & Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambarnath MIDC Road, Thane-421506 Maharashtra, India.

Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallurgy • Corrosion Testing • NDT Services

TEST REPORT

Page 1 of 1

Lab Ref.: A7115-1
Customer Name: M/s. SAMS BATH FIXTURES PVT LTD.
& Address : Unit No.13 & 31, Sonal Industrial Estate, Pathak Road, Bhayandar (E), Thane-401105
#Sample Description: Angle Valve
#Material Dimension: 1/2"
#Marking: SAMS-AVSTICK-035

Report Date :
Sample Received on :

Discipline : Mechanical

Group : Mechanical Properties of Metals

Salt Spray Test Test Method : ASTM B117:2018

	Result
Solution	5% NaCl Solution
PH of Solution	6.8-7.2
Temperature	35±1°C
Duration	24 Hours

Loading Date

Unloading Date

Remarks

The Corrosion has not seen on sample's Surface after testing

Coating Thickness (µm)

Test Date :

	Result
1.	0.354
2.	0.348
3.	0.347
Average Micron (µm)	0.350

.....END OF REPORT.....



ATIS/FM/39

Mr. Kushal Pandey
Testing In-charge

Reviewed By

Mr. Munna Singh
Lab Head

Authorised Signatory



Scope & Certificate

DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # information provided by customer.

DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,
i.e. Acceptance Limit (AL)= Tolerance Limit (TL), Results will be rounded off appropriately and will be directly compared with the specification



ASIAN TESTING & INSPECTION SERVICES

Approved by Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambamath MIDC Road, Thane-421506 Maharashtra, India.
Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallography • Corrosion Testing



TC-11632

TEST REPORT

Page 1 of 1

Lab Ref.: A7117
Customer Name: M/s. SAMS BATH FIXTURES PVT LTD.
& Address: Unit No.13 & 31, Sonal Industrial Estate, Pathak Road, Bhayandar (E), Thane-401105
#Sample Description: SS Connection Pipe
#Specification: IS 319:2007 Gr. 1
#Material Dimension: 18"
#Marking: SAMS-SSCCP18-051

ULR No.: TC1163224000002985F

Report Date:

Sample Received on:

Discipline: Chemical
Group: Metal & Alloys

Spectro Chemical Analysis

Test Date:

Equipment: Hitachi FM Expert Cal. Dt:

Due Dt:

	Result	Requirement	Test Method
% Lead (Pb)	3.12	2.00-3.50	BS EN 15079 A2:2015
% Iron (Fe)	0.278	0.35 max.	BS EN 15079 A2:2015
% Zinc (Zn)	Remainder	Remainder	BS EN 15079 A2:2015

Remark: The above result(s) meets the specified requirements of IS 319:2007 Gr. 1 with respect to elements analysed.

.....END OF REPORT



ATIS/FM/39

Mr. Kushal Pandey
Testing In-charge

Reviewed By

Mr. Munna Singh
Lab Head

Authorised Signatory



Scope & Certificate

DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # Information provided by customer.

DECISION RULE TO STATE THE CONFORMITY STATEMENT:

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,
i.e. Acceptance Limit (AL)= Tolerance Limit (TL). Results will be rounded off appropriately and will be directly compared with the specification



ASIAN TESTING & INSPECTION SERVICES

Approved by Govt. Organizations & Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambarnath MIDC Road, Thane-421506 Maharashtra, India.

Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallography • Corrosion Testing • NDT Services

TEST REPORT

Page 1 of 1

Lab Ref.: A7117-1
Customer Name: M/s. SAMS BATH FIXTURES PVT LTD.
& Address : Unit No.13 & 31, Sonal Industrial Estate, Pathak Road, Bhayandar (E), Thane-401105
#Sample Description: SS Connection Pipe
#Specification : IS 319:2007 Gr. 1
#Material Dimension 18"
#Marking SAMS-SSCCP18-051

Report Date :
Sample Received on :

Spectro Chemical Analysis

Equipment : Hitachi FM Expert Cal. Dt:

Test Date :

Due Dt.:

	Result	Requirement
%Copper (Cu)	56.17	56.00-59.00

Remark: The above result(s) meets the specified requirements of IS 319:2007 Gr. 1 with respect to Copper .

.....END OF REPORT.....



ATIS/FM/39

Mr. Kushal Pandey
Testing In-charge

Reviewed By

Mr. Munna Singh
Lab Head

Authorised Signatory



Scope & Certificate

DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # information provided by customer.

DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,
i.e. Acceptance Limit (AL)= Tolerance Limit (TL). Results will be rounded off appropriately and will be directly compared with the specification



ASIAN TESTING & INSPECTION SERVICES

Approved by Govt. Organizations & Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambarnath MIDC Road, Thane-421506 Maharashtra, India.

Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallography • Corrosion Testing • NDT Services
TEST REPORT
Page 1 of 1

Lab Ref.: A7119-1
Customer Name: M/s. SAMS BATH FIXTURES PVT LTD.
& Address : Unit No.13 & 31,Sonal Industrial Estate,Pathak
Road,Bhayandar (E),Thane-401105
#Sample Description: Extention Nipple
#Material Dimension: 2"
#Marking: SAMS-EXT-003

Report Date :
Sample Received on :

Discipline : Mechanical
Group : Mechanical Properties of Metals

Destructive Test

Test Date :

Destruction	Result
Angle of Destruction	By Hammer
Observation	Closed
Remark	No cracks and no rupture found.
	Satisfactory

Coating Thickness (µm)

Test Date :

	Result
1.	0.378
2.	0.357
3.	0.346
Average Micron (µm)	0.360

.....END OF REPORT.....



ATIS/FM/39

Mr. Kushal Pandey
Testing In-charge

Reviewed By

Mr. Munna Singh
Lab Head

Authorised Signatory



Scope & Certificate

DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # information provided by customer.

DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,
i.e. Acceptance Limit (AL)= Tolerance Limit (TL), Results will be rounded off
appropriately and will be directly compared with the specification