



ASIAN TESTING & INSPECTION SERVICES

Approved by Govt. Organizations & Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambarnath MIDC Road, Thane-421506 Maharashtra, India.
Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallography • Corrosion Testing • NDT Services

TEST REPORT

Page 1 of 1

Lab Ref.: A7115-1
Customer Name & Address : M/s. SAMS BATH FIXTURES PVT LTD.
Unit No.13 & 31,Sonal Industrial Estate,Pathak
Road,Bhayandar (E),Thane-401105
#Sample Description: Angle Valve
#Material Dimension 1/2"
#Marking SAMS-AVSTICK-035

Report Date :
Sample Received on :

Discipline : Mechanical

Group : Mechanical Properties of Metals

Salt Spray Test Test Method : ASTM B117:2018

	Result
Solution	5% NaCl Solution
PH of Solution	6.8-7.2
Temperature	35±1°C
Duration	24 Hours
Loading Date	22/11/2024 Time 3:30PM
Unloading Date	23/11/2024 Time 3:30PM
Remarks	The Corrosion has not seen on sample's Surface after testing

.....END OF REPORT.....



ATIS/FM/39

Mr. Kushal Pandey
Testing In-charge

Reviewed By

Mr. Munna Singh
Lab Head

Authorised Signatory



Scope & Certificate

DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. #information provided by customer.

DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,
i.e. Acceptance Limit (AL)= Tolerance Limit (TL), Results will be rounded off
appropriately and will be directly compared with the specification