



# ASIAN TESTING & INSPECTION SERVICES

Approved by Govt. Organizations & Third Party Inspection Agencies.

Unit No. 02 & 03, Near Ganesh Temple, Nevali Naka, Kalyan East, Ambarnath MIDC Road, Thane-421506 Maharashtra, India.

Email: asian.testinglab@yahoo.com Tel: +91 88509 19087 / 84259 16509 • MSME-UDYAM Registration No:MH-33-0255108

Chemical • Mechanical • Metallography • Corrosion Testing • NDT Services

## TEST REPORT

Page 1 of 1

Lab Ref.: A7117-1  
Customer Name: M/s. SAMS BATH FIXTURES PVT LTD.  
& Address: Unit No.13 & 31, Sonal Industrial Estate, Pathak Road, Bhayandar (E), Thane-401105  
#Sample Description: Connection Pipe  
#Specification: IS 319:2007 Gr. 1  
#Material Dimension: 18"  
#Marking: SAMS-SSCCP18-051

Report Date :  
Sample Received on :

### Spectro Chemical Analysis

Equipment : Hitachi FM Expert Cal. Dt:

Test Date :

Due Dt.:

	Result	Requirement
%Copper (Cu)	56.17	56.00-59.00

Remark: The above result(s) meets the specified requirements of IS 319:2007 Gr. 1 with respect to Copper .

.....END OF REPORT.....



ATIS/FM/39

Mr. Kushal Pandey  
Testing In-charge

Reviewed By

Mr. Munna Singh  
Lab Head

Authorised Signatory



Scope & Certificate

#### DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # Information provided by customer.

#### DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019,  
i.e. Acceptance Limit (AL)= Tolerance Limit (TL), Results will be rounded off appropriately and will be directly compared with the specification