

## Test Report

Page 1 of 1

T.C. No. : A7115-A7119

Issued To. : SAMS BATH FIXTURES PVT LTD.

Report Date :

Unit No.13 & 31,Sonal Industrial Estate,Pathak Road,Bhayandar (E),Thane-401105

# Challan Ref. Date : ---

#Description of Sample : Below mentioned

Sample Received :

#Specification : --

Test Started on :

#PO NO./Date : --

Test Completed on :

#Qty. : 05 Nos.

### HYDRO PRESSURE TEST

Test Method : ASTM E1003 -13(2018)

Equipment: Compressor Pump with Pressure Dial Gauge 0 – 4000Psi

Test performed on :

Dial Gauge ID.: CORR-36, Cal. Due Dt.:

SR. No.	DESCRIPTION	Marking	CLIENT REQD.PRESSURE Bar(psi)	QTY. IN No.
1	Angle Valve (1/2")	SAMS-AVSTICK-035	10(145.04)	1
2	PVC Connection Pipe(18")	SAMS-PVCCP18-048	10(145.04)	1
3	Connection Pipe(18")	SAMS-SSCCP18-051	10(145.04)	1
4	SS Tube(1Mtr)	SAMS-SSTUB1MTR-070	10(145.04)	1
5	Extention Nipple(2")	SAMS-EXT-003	10(145.04)	1

**Note :** Pressure Holding Time 10 Sec.


**Result :** 1- No Leakage & No Pressure Drop Observed.

**Remark:** Satisfactory

\*\*\*\*\*END OF TEST REPORT\*\*\*\*\*

  
**Mr. Kushal Pandey**  
 Testing In-charge

Checked By

  
**Mr. Munna Singh**  
 Lab Head

Authorised signatory By

#### DISCLAIMER:

1. The reported test results related only to the sample(s) provided and tested.
2. The above sample(s) are not drawn by the laboratory.
3. The Lab is not responsible for any financial / legal liability arising out of any errors or omissions.
4. This test report cannot be reproduced either in part or in full without the written approval of the lab.
5. # information provided by customer.

#### DECISION RULE TO STATE THE CONFORMITY STATEMENT :

SIMPLE ACCEPTANCE RULE, as per ILAC G-8 : 2019, i.e. Acceptance Limit (AL)= Tolerance Limit (TL), Results will be rounded off appropriately and will be directly compared with the specification